

Devices:

```

+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+
+-----+-----+
|      id |      type | root |      parent_id | serial_number | admin_state |
oper_status | connect_status | parent_port_no |      host_and_port |      reason |
proxy_address.device_id | proxy_address.onu_id | proxy_address.onu_session_id |
+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+
+-----+-----+
| 0001ee9b09f7f1af |      openolt | True | 000100000ac014ce | EC1838000853
|  ENABLED |  ACTIVE |  REACHABLE |      | 10.192.20.206:9191 |
|      |      |      |      | [0m
| 0001d4f2072f41a3 | brcm_openomci_onu |      | 0001ee9b09f7f1af |
ALPHe3d1cfa7 |  ENABLED |  ACTIVE |  REACHABLE |  536870912 |
| omci-flows-deleted |      0001ee9b09f7f1af |      1 |      1 |
[0m
+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+
+-----+-----+

```

Device [1m[32m0001ee9b09f7f1af[0m (type: [34mopenolt[0m)

Flows (6):

```

+-----+-----+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+-----+
+-----+-----+
| table_id | priority |      cookie |      in_port | vlan_vid | eth_type | ip_proto | udp_src |
udp_dst |      metadata | set_vlan_vid | pop_vlan | push_vlan |      output | goto-table |
|
+-----+-----+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+-----+
+-----+-----+
|      0 | 10000 | ~203231e2 |      16 | 4091 | 888E |      |      |
|      |      |      | CONTROLLER |      | [0m
|      0 | 10000 | ~203231e2 | CONTROLLER | 4090 |      |      |      |
|      |      |      |      |      | 16 |      | [0m
|      0 | 10000 | ~52d6e3e8 |      16 |      | 800 | 17 | 68 | 67 |

```

			CONTROLLER		[[0m				
1	1000	~95498d06	16	999					
111		8100	65536		[[0m				
0	10000	~203231e2	16	999	888E				
			CONTROLLER		[[0m				
0	1000	~59e43e09	65536	111					
4290672328720			Yes			1	[[0m		

Device ports:

port_no	label	type	admin_state	oper_status	device_id	peers
536870912	pon0	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
65536	nni-65536	ETHERNET_NNI	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870913	pon1	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870914	pon2	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870915	pon3	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870916	pon4	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870917	pon5	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870918	pon6	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870919	pon7	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870920	pon8	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870921	pon9	PON_OLT	ENABLED	ACTIVE		
0001ee9b09f7f1af						[[0m
536870922	pon10	PON_OLT	ENABLED	ACTIVE		

```

0001ee9b09f7f1af | [[0m
| 536870923 | pon11 | PON_OLT | ENABLED | ACTIVE |
0001ee9b09f7f1af | [[0m
| 536870924 | pon12 | PON_OLT | ENABLED | ACTIVE |
0001ee9b09f7f1af | [[0m
| 536870925 | pon13 | PON_OLT | ENABLED | ACTIVE |
0001ee9b09f7f1af | [[0m
| 536870926 | pon14 | PON_OLT | ENABLED | ACTIVE |
0001ee9b09f7f1af | [[0m
| 536870927 | pon15 | PON_OLT | ENABLED | ACTIVE |
0001ee9b09f7f1af | [[0m
| 16 | uni-16 | ETHERNET_UNI | ENABLED | ACTIVE | 0001ee9b09f7f1af
| [{'port_no': 100, 'device_id': u'0001d4f2072f41a3'}] [[0m

```

```

+-----+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+-----+

```

Logical Device [1m[32m000100000ac014ce[0m (type: [34mn/a[0m)

Flows (3):

```

+-----+-----+-----+-----+-----+-----+-----+
+-----+-----+
| table_id | priority | cookie | in_port | eth_type | ip_proto | udp_src | udp_dst |
output |
+-----+-----+-----+-----+-----+-----+-----+
+-----+-----+
| 0 | 10000 | ~09c7aee4 | 65536 | 88CC | | | |
CONTROLLER |[0m
| 0 | 10000 | ~ea2d38c2 | 65536 | 800 | 17 | 67 | 68 |
CONTROLLER |[0m
| 0 | 10000 | ~2aedf8c3 | 16 | 888E | | | | CONTROLLER
|[0m

```

```

+-----+-----+-----+-----+-----+-----+-----+
+-----+-----+

```

Logical device ports:

```

+-----+-----+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+-----+
+-----+-----+-----+
| id | device_id | device_port_no | root_port | ofp_port.port_no |
ofp_port.hw_addr | ofp_port.name | ofp_port.state | ofp_port.curr |
ofp_port.curr_speed | ofp_port_stats.port_no |
+-----+-----+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+-----+
+-----+-----+-----+
| nni-65536 | 0001ee9b09f7f1af | 65536 | True | 65536 | [0L, 0L,

```

```

0L, 1L, 0L, 0L] | nni-65536 | 4 | 4128 | 32 |
65536 |[0m
| uni-16 | 0001d4f2072f41a3 | 16 | | 16 | [8L, 0L, 0L, 0L,
0L, 16L] | ALPHe3d1cfa7 | 4 | 4160 | 64 | |
[0m
+-----+-----+-----+-----+-----+
+-----+-----+-----+-----+-----+
+-----+-----+

```

```

=====
=====

```

apps -a -s

- * 5 org.onosproject.optical-model 1.13.5 Optical Network Model
- * 6 org.onosproject.openflow-base 1.13.5 OpenFlow Base Provider
- * 7 org.onosproject.drivers 1.13.5 Default Drivers
- * 14 org.onosproject.route-service 1.13.5 Route Service Server
- * 15 org.onosproject.mcast 1.13.5 Multicast traffic control
- * 16 org.onosproject.segmentrouting 1.13.5 Segment Routing
- * 24 org.onosproject.lldpprovider 1.13.5 LLDP Link Provider
- * 37 org.onosproject.hostprovider 1.13.5 Host Location Provider
- * 38 org.onosproject.openflow 1.13.5 OpenFlow Provider Suite
- * 81 org.onosproject.netcfgghostprovider 1.13.5 Network Config Host Provider
- * 170 org.opencord.sadis 2.2.0.SNAPSHOT Subscriber And Device Information App
- * 171 org.opencord.aaa 1.8.0.SNAPSHOT AAA App
- * 172 org.opencord.kafka 1.0.0 Kafka integration app
- * 177 org.opencord.olt 2.1.0.SNAPSHOT Optical Line Terminal App
- * 178 org.opencord.dhcpl2relay 1.5.0.SNAPSHOT DHCP Relay Agent App

```
=====
```

devices

```

id=of:000000000ac014ce, available=true, local-status=connected 5m16s ago,
role=MASTER, type=SWITCH, mfr=VOLTHA Project, hw=, sw=,
serial=EC1838000853, chassis=ac014ce, driver=voltha,
channelId=10.233.75.22:41442, locType=none,
managementAddress=10.233.75.22, name=olt-1, protocol=OF_13
id=of:0000cc37ab5b6da8, available=true, local-status=connected 20m9s ago,
role=MASTER, type=SWITCH, mfr=Accton Corp., hw=x86-64-accton-
as6712-32x-r0, sw=ofdpa 3.0.5.5+accton1.7-1, serial=671232X1534021,
chassis=cc37ab5b6da8, driver=ofdpa3, channelId=10.233.102.128:40728,
locType=none, managementAddress=10.233.102.128, name=Fabric Switch - 1,
protocol=OF_13

```

```
=====
```

ports

id=of:00000000ac014ce, available=true, local-status=connected 5m17s ago, role=MASTER, type=SWITCH, mfr=VOLTHA Project, hw=, sw=, serial=EC1838000853, chassis=ac014ce, driver=voltha, channelId=10.233.75.22:41442, locType=none, managementAddress=10.233.75.22, name=olt-1, protocol=OF_13
port=16, state=enabled, type=fiber, speed=0 , adminState=enabled, portMac=08:00:00:00:00:10, portName=ALPHe3d1cfa7
port=65536, state=enabled, type=fiber, speed=0 , adminState=enabled, portMac=00:00:00:01:00:00, portName=nni-65536

id=of:0000cc37ab5b6da8, available=true, local-status=connected 20m10s ago, role=MASTER, type=SWITCH, mfr=Accton Corp., hw=x86-64-accton-as6712-32x-r0, sw=ofdpa 3.0.5.5+accton1.7-1, serial=671232X1534021, chassis=cc37ab5b6da8, driver=ofdpa3, channelId=10.233.102.128:40728, locType=none, managementAddress=10.233.102.128, name=Fabric Switch - 1, protocol=OF_13

port=1, state=enabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port1
port=2, state=enabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port2
port=3, state=enabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port3
port=4, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port4
port=5, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port5
port=6, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port6
port=7, state=enabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port7
port=8, state=enabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port8
port=9, state=enabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port9
port=10, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port10
port=11, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port11
port=12, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port12
port=13, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port13
port=14, state=disabled, type=fiber, speed=40000 , adminState=enabled, portMac=cc:37:ab:5b:6d:a9, portName=port14

port=15, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port15
port=16, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port16
port=17, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port17
port=18, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port18
port=19, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port19
port=20, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port20
port=21, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port21
port=22, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port22
port=23, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port23
port=24, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port24
port=25, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port25
port=26, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port26
port=27, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port27
port=28, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port28
port=29, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port29
port=30, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port30
port=31, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port31
port=32, state=disabled, type=fiber, speed=40000 , adminState=enabled,
portMac=cc:37:ab:5b:6d:a9, portName=port32

=====

flows -s

deviceId=of:000000000ac014ce, flowRuleCount=3

ADDED, bytes=0, packets=0, table=0, priority=10000, selector=[IN_PORT:
65536, ETH_TYPE:lldp], treatment=[immediate=[OUTPUT:CONTROLLER]]

ADDED, bytes=0, packets=0, table=0, priority=10000, selector=[IN_PORT:16,
ETH_TYPE:epol], treatment=[immediate=[OUTPUT:CONTROLLER]]

ADDED, bytes=0, packets=0, table=0, priority=10000, selector=[IN_PORT:65536, ETH_TYPE:ipv4, IP_PROTO:17, UDP_SRC:67, UDP_DST:68], treatment=[immediate=[OUTPUT:CONTROLLER]]
deviceId=of:0000cc37ab5b6da8, flowRuleCount=65

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:9, VLAN_VID:4094], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:2, VLAN_VID:4090], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:1, VLAN_VID:4094], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:8, VLAN_VID:4094], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:1, VLAN_VID:4090], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:7, VLAN_VID:4090], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:3, VLAN_VID:None], treatment=[immediate=[VLAN_ID:4094], transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:1, VLAN_VID:None], treatment=[immediate=[VLAN_ID:4094], transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:8, VLAN_VID:None], treatment=[immediate=[VLAN_ID:4094], transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:7, VLAN_VID:4094], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:2, VLAN_VID:4094], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:2, VLAN_VID:None], treatment=[immediate=[VLAN_ID:4094], transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:7, VLAN_VID:None], treatment=[immediate=[VLAN_ID:4094], transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:3, VLAN_VID:4090], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:9, VLAN_VID:4090], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:3, VLAN_VID:4094], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:8, VLAN_VID:4090], treatment=[transition=TABLE:20]

ADDED, bytes=0, packets=0, table=10, priority=32768, selector=[IN_PORT:9, VLAN_VID:None], treatment=[immediate=[VLAN_ID:4094], transition=TABLE:20]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:9, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4094], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:2, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4090], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:2, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4094], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:9, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4090], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:8, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4094], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:3, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4090], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:3, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4090], treatment=[transition=TABLE:23]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:1, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4094], treatment=[transition=TABLE:23]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:7, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4090], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:2, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4094], treatment=[transition=TABLE:23]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:7, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4094], treatment=[transition=TABLE:23]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:2, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4090], treatment=[transition=TABLE:23]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:7, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4090], treatment=[transition=TABLE:23]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:1, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4094], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:1, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4090], treatment=[transition=TABLE:30]

ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:9,

ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:8,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4090],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:7,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4090],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:7,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:9,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4094],
treatment=[transition=TABLE:23]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:8,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4090],
treatment=[transition=TABLE:23]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:2,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:3,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:8,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:3,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:1,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4090],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:3,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4094],
treatment=[transition=TABLE:23]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:1,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4090],
treatment=[transition=TABLE:23]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:8,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4090],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:2,
ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4090],

treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:9, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4090],
treatment=[transition=TABLE:23]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:3, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4090],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:9, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4090],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:7, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv4, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:8, ETH_DST:00:00:00:00:00:03, ETH_TYPE:mpls_unicast, VLAN_VID:4094],
treatment=[transition=TABLE:23]
ADDED, bytes=0, packets=0, table=20, priority=32768, selector=[IN_PORT:1, ETH_DST:00:00:00:00:00:03, ETH_TYPE:ipv6, VLAN_VID:4094],
treatment=[transition=TABLE:30]
ADDED, bytes=2154, packets=6, table=60, priority=61000, selector=[IN_PORT:8, ETH_TYPE:ipv4, IP_PROTO:17, UDP_SRC:67, UDP_DST:68],
treatment=[immediate=[OUTPUT:CONTROLLER], clearDeferred]
ADDED, bytes=14592, packets=152, table=60, priority=40000, selector=[ETH_TYPE:bddp], treatment=[immediate=[OUTPUT:CONTROLLER], clearDeferred]
ADDED, bytes=0, packets=0, table=60, priority=40000, selector=[ETH_TYPE:eapol], treatment=[immediate=[OUTPUT:CONTROLLER], clearDeferred]
ADDED, bytes=14592, packets=152, table=60, priority=40000, selector=[ETH_TYPE:lldp], treatment=[immediate=[OUTPUT:CONTROLLER], clearDeferred]
ADDED, bytes=0, packets=0, table=60, priority=40000, selector=[ETH_TYPE:ipv4, IPV4_DST:192.168.9.24/32], treatment=[immediate=[OUTPUT:CONTROLLER], clearDeferred]
ADDED, bytes=0, packets=0, table=60, priority=40000, selector=[ETH_TYPE:ipv6, IPV6_DST:fe80::200:ff:fe00:3/128], treatment=[immediate=[OUTPUT:CONTROLLER], clearDeferred]
ADDED, bytes=94, packets=1, table=60, priority=30000, selector=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:136], treatment=[immediate=[OUTPUT:CONTROLLER]]
ADDED, bytes=528, packets=6, table=60, priority=30000, selector=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:135], treatment=[immediate=[OUTPUT:CONTROLLER]]

ADDED, bytes=0, packets=0, table=60, priority=30000,
selector=[ETH_TYPE:arp], treatment=[immediate=[OUTPUT:CONTROLLER]]

ADDED, bytes=0, packets=0, table=60, priority=30000,
selector=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:134],
treatment=[immediate=[OUTPUT:CONTROLLER]]

ADDED, bytes=1440, packets=18, table=60, priority=30000,
selector=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:133],
treatment=[immediate=[OUTPUT:CONTROLLER]]

=====

+++++ONOS LOGS+++++

2019-03-19T13:42:22.504683125Z 2019-03-19 13:42:22,503 | INFO | onos-of-worker-0 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received port status message from 00:00:cc:37:ab:5b:6d:a8/7: OFPortStatusVer13(xid=0, reason=MODIFY, desc=OFPortDescVer13(portNo=7, hwAddr=cc:37:ab:5b:6d:a9, name=port7, config=[], state=[], curr=[PF_FIBER, PF_40GB_FD], advertised=[], supported=[PF_10MB_FD, PF_100MB_FD, PF_1GB_FD, PF_10GB_FD, PF_FIBER, PF_AUTONEG, PF_PAUSE, PF_PAUSE_ASYM, PF_40GB_FD, PF_OTHER], peer=[], currSpeed=40000000, maxSpeed=40000000))

2019-03-19T13:42:22.506111082Z 2019-03-19 13:42:22,505 | INFO | onos-of-worker-0 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:0000cc37ab5b6da8 port 7 status changed

2019-03-19T13:42:22.507264878Z 2019-03-19 13:42:22,506 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:0000cc37ab5b6da8, type=SWITCH, manufacturer=Accton Corp., hwVersion=x86-64-accton-as6712-32x-r0, swVersion=ofdpa 3.0.5.5+accton1.7-1, serialNumber=671232X1534021, driver=ofdpa3}/DefaultPort{element=of:0000cc37ab5b6da8, number=7, isEnabled=true, type=FIBER, portSpeed=40000, annotations={adminState=enabled, portName=port7, portMac=cc:37:ab:5b:6d:a9}} -> PORT_UPDATED

2019-03-19T13:42:22.507575398Z 2019-03-19 13:42:22,507 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Switchport of:0000cc37ab5b6da8/7 enabled..programming filters

2019-03-19T13:42:55.712153351Z 2019-03-19 13:42:55,711 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | New switch connection from /10.233.75.22:41442

2019-03-19T13:42:55.71552907Z 2019-03-19 13:42:55,715 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Sending OF_13 Hello to /10.233.75.22:41442

2019-03-19T13:42:55.74331647Z 2019-03-19 13:42:55,742 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received meter features from [/10.233.75.22:41442 DPID[00:00:00:00:0a:c0:14:ce]] with max meters: 4294967295

2019-03-19T13:42:55.751508101Z 2019-03-19 13:42:55,751 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received switch description reply OFDescStatsReplyVer13(xid=4294967288, flags=[], mfrDesc=VOLTHA Project, hwDesc=, swDesc=, serialNum=EC1838000853, dpDesc=) from switch at / 10.233.75.22:41442

2019-03-19T13:42:55.752286614Z 2019-03-19 13:42:55,751 | INFO | onos-of-worker-2 | Controller | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Driver 'voltha' assigned to device 00:00:00:00:0a:c0:14:ce

2019-03-19T13:42:55.753652385Z 2019-03-19 13:42:55,753 | INFO | onos-of-worker-2 | ntrollerImpl\$OpenFlowSwitchAgent | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Added switch 00:00:00:00:0a:c0:14:ce

2019-03-19T13:42:55.760875427Z 2019-03-19 13:42:55,760 | INFO | onos-of-worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Local role is MASTER for of:000000000ac014ce

2019-03-19T13:42:55.761416955Z 2019-03-19 13:42:55,761 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** MASTERSHIP CHANGED Invalidating shouldProgram cache for of:000000000ac014ce/pair=Optional.empty due to change

2019-03-19T13:42:55.766647456Z 2019-03-19 13:42:55,766 | INFO | onos-of-worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:000000000ac014ce connected

2019-03-19T13:42:55.767749375Z 2019-03-19 13:42:55,767 | INFO | onos-of-worker-2 | PortStatsCollector | 165 - org.onosproject.onos-providers-openflow-device - 1.13.5 | Starting Port Stats collection thread for 00:00:00:00:0a:c0:14:ce

2019-03-19T13:42:55.767789389Z 2019-03-19 13:42:55,767 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** DEVICE UP Processing device event DEVICE_AVAILABILITY_CHANGED for available device of:000000000ac014ce

2019-03-19T13:42:55.768096174Z 2019-03-19 13:42:55,767 | INFO | spatch-topology0 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Invalidating cached pipeline behaviour for of:000000000ac014ce

2019-03-19T13:42:55.768106006Z 2019-03-19 13:42:55,767 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** DEVICE ADDED with ID of:000000000ac014ce

2019-03-19T13:42:55.768376289Z 2019-03-19 13:42:55,768 | INFO | onos-of-worker-2 | MeterStatsCollector | 169 - org.onosproject.onos-providers-

openflow-meter - 1.13.5 | Starting Meter Stats collection thread for
00:00:00:00:0a:c0:14:ce
2019-03-19T13:42:55.768397053Z 2019-03-19 13:42:55,768 | WARN | sr-event-
main-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | getRouterIpv4 fails for device: of:
000000000ac014ce. Aborting populatelpPunts.
2019-03-19T13:42:55.768403529Z 2019-03-19 13:42:55,768 | INFO | spatch-
topology0 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Driver voltha bound to device of:000000000ac014ce ... initializing
driver
2019-03-19T13:42:55.768695455Z 2019-03-19 13:42:55,768 | INFO | ispatch-
default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 |
Got AccessDeviceEvent: DEVICE_CONNECTED
2019-03-19T13:42:55.772775606Z 2019-03-19 13:42:55,772 | ERROR | tive-
installer-1 | OltPipeline | 170 - org.onosproject.onos-drivers-default -
1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=34647077, op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:arp]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}
2019-03-19T13:42:55.773108309Z 2019-03-19 13:42:55,772 | ERROR | tive-
installer-0 | OltPipeline | 170 - org.onosproject.onos-drivers-default -
1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=-1216580183, op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58,
ICMPV6_TYPE:134]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}
2019-03-19T13:42:55.773146685Z 2019-03-19 13:42:55,772 | WARN | sr-event-
main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Device configuration unavailable. Device of:
000000000ac014ce will be processed after configuration.
2019-03-19T13:42:55.773399931Z 2019-03-19 13:42:55,772 | WARN | tive-
installer-1 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=34647077,
op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:arp]},

treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.773438422Z 2019-03-19 13:42:55,773 | WARN | tive-installer-0 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=-1216580183, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:134]}}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.773452581Z 2019-03-19 13:42:55,772 | INFO | ispatch-default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 | Got AccessDeviceEvent: UNI_REMOVED
2019-03-19T13:42:55.773666564Z 2019-03-19 13:42:55,772 | ERROR | tive-installer-2 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified: DefaultForwardingObjective{id=-536521813, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:136]}}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}
2019-03-19T13:42:55.773695134Z 2019-03-19 13:42:55,773 | INFO | onos-of-worker-2 | GroupStatsCollector | 168 - org.onosproject.onos-providers-openflow-group - 1.13.5 | Starting Group Stats collection thread for 00:00:00:00:0a:c0:14:ce
2019-03-19T13:42:55.77370659Z 2019-03-19 13:42:55,773 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** DEVICE UP Processing device event DEVICE_UPDATED for available device of:000000000ac014ce
2019-03-19T13:42:55.773879182Z 2019-03-19 13:42:55,772 | ERROR | tive-installer-3 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified: DefaultForwardingObjective{id=590874280, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58,

ICMPV6_TYPE:133}},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}
2019-03-19T13:42:55.773916524Z 2019-03-19 13:42:55,773 | WARN | tive-
installer-1 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt ARP to
of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.774012295Z 2019-03-19 13:42:55,773 | WARN | tive-
installer-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to
of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.774193752Z 2019-03-19 13:42:55,773 | INFO | sr-event-
main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | ** DEVICE ADDED with ID of:000000000ac014ce
2019-03-19T13:42:55.774217743Z 2019-03-19 13:42:55,773 | WARN | tive-
installer-3 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=590874280,
op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58,
ICMPV6_TYPE:133]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.774407669Z 2019-03-19 13:42:55,773 | WARN | tive-
installer-2 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=-536521813,
op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58,
ICMPV6_TYPE:136]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.774420055Z 2019-03-19 13:42:55,773 | INFO | onos-of-
worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-
openflow-ctl - 1.13.5 | Processing 0 pending port status messages for
00:00:00:00:0a:c0:14:ce

2019-03-19T13:42:55.774507066Z 2019-03-19 13:42:55,774 | WARN | tive-installer-3 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS

2019-03-19T13:42:55.774515208Z 2019-03-19 13:42:55,774 | WARN | sr-event-main-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | getRouterIpv4 fails for device: of:000000000ac014ce. Aborting populatelpunts.

2019-03-19T13:42:55.774957093Z 2019-03-19 13:42:55,774 | WARN | tive-installer-2 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS

2019-03-19T13:42:55.78127402Z 2019-03-19 13:42:55,774 | ERROR | tive-installer-1 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:

DefaultForwardingObjective{id=1270932650, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:135]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}

2019-03-19T13:42:55.781304477Z 2019-03-19 13:42:55,780 | ERROR | tive-installer-0 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:

DefaultForwardingObjective{id=34647077, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:arp]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}

2019-03-19T13:42:55.781315429Z 2019-03-19 13:42:55,781 | INFO | onos-of-worker-2 | ntrollerImpl\$OpenFlowSwitchAgent | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Transitioned switch 00:00:00:00:0a:c0:14:ce to MASTER

2019-03-19T13:42:55.781446737Z 2019-03-19 13:42:55,781 | WARN | tive-installer-1 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=1270932650, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:135]},

treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.781471172Z 2019-03-19 13:42:55,781 | WARN | tive-installer-0 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=34647077, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:arp]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.781480222Z 2019-03-19 13:42:55,781 | WARN | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Device configuration unavailable. Device of: 000000000ac014ce will be processed after configuration.
2019-03-19T13:42:55.78157786Z 2019-03-19 13:42:55,781 | ERROR | tive-installer-3 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified: DefaultForwardingObjective{id=590874280, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:133]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}
2019-03-19T13:42:55.781588339Z 2019-03-19 13:42:55,781 | WARN | tive-installer-1 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.781796767Z 2019-03-19 13:42:55,781 | ERROR | tive-installer-2 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified: DefaultForwardingObjective{id=-536521813, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:136]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE,

appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}

2019-03-19T13:42:55.781835622Z 2019-03-19 13:42:55,781 | WARN | tive-installer-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt ARP to of:000000000ac014ce: BADPARAMS

2019-03-19T13:42:55.78184456Z 2019-03-19 13:42:55,781 | WARN | tive-installer-3 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=590874280, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:133]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS

2019-03-19T13:42:55.78195473Z 2019-03-19 13:42:55,781 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:000000000ac014ce, type=SWITCH, manufacturer=VOLTHA Project, hwVersion=, swVersion=, serialNumber=EC1838000853, driver=voltha}/ DefaultPort{element=of:000000000ac014ce, number=65536, isEnabled=true, type=FIBER, portSpeed=0, annotations={adminState=enabled, portName=nni-65536, portMac=00:00:00:01:00:00}} -> PORT_UPDATED

2019-03-19T13:42:55.781976418Z 2019-03-19 13:42:55,781 | ERROR | tive-installer-1 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified: DefaultForwardingObjective{id=-1216580183, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:134]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}

2019-03-19T13:42:55.782087849Z 2019-03-19 13:42:55,781 | WARN | tive-installer-3 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS

2019-03-19T13:42:55.782101406Z 2019-03-19 13:42:55,781 | WARN | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Device configuration uploading. Not handling port

event fordev: of:00000000ac014ce port: 65536
2019-03-19T13:42:55.78227988Z 2019-03-19 13:42:55,781 | WARN | tive-
installer-2 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=-536521813,
op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58,
ICMPV6_TYPE:136]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.782302654Z 2019-03-19 13:42:55,782 | WARN | tive-
installer-1 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=-1216580183,
op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58,
ICMPV6_TYPE:134]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.782494165Z 2019-03-19 13:42:55,782 | ERROR | tive-
installer-0 | OltPipeline | 170 - org.onosproject.onos-drivers-default -
1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=1270932650, op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58,
ICMPV6_TYPE:135]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting},
permanent=true, timeout=0}
2019-03-19T13:42:55.782546521Z 2019-03-19 13:42:55,782 | WARN | tive-
installer-2 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to
of:00000000ac014ce: BADPARAMS
2019-03-19T13:42:55.782556598Z 2019-03-19 13:42:55,782 | WARN | tive-
installer-1 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to
of:00000000ac014ce: BADPARAMS
2019-03-19T13:42:55.782567163Z 2019-03-19 13:42:55,782 | INFO | ice-

installer-30 | DeviceFlowTable | 132 - org.onosproject.onos-core-dist - 1.13.5 | Synchronizing device of:000000000ac014ce flows for term 2
2019-03-19T13:42:55.782908267Z 2019-03-19 13:42:55,782 | WARN | tive-installer-0 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=1270932650, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:135]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.783206166Z 2019-03-19 13:42:55,782 | INFO | nos-topo-build-6 | TopologyManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Topology DefaultTopology{time=2135770023237936, creationTime=1553002975780, computeCost=293817, clusters=2, devices=2, links=0} changed
2019-03-19T13:42:55.783473175Z 2019-03-19 13:42:55,783 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Processing topology event TOPOLOGY_CHANGED, topology age 2135770023237936, reasons 1
2019-03-19T13:42:55.783584411Z 2019-03-19 13:42:55,783 | WARN | tive-installer-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.784524461Z 2019-03-19 13:42:55,784 | ERROR | tive-installer-3 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=1156990345, op=ADD, priority=40000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:eapol]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=true, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=1, name=org.onosproject.core}, permanent=true, timeout=0}
2019-03-19T13:42:55.784557529Z 2019-03-19 13:42:55,784 | ERROR | tive-installer-2 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=-2062265795, op=ADD, priority=40000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:bddp]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=true, StatTrigger=null,

metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=1, name=org.onosproject.core}, permanent=true,
timeout=0}

2019-03-19T13:42:55.784697365Z 2019-03-19 13:42:55,784 | ERROR | tive-
installer-1 | OltPipeline | 170 - org.onosproject.onos-drivers-default -
1.13.5 | Forwarding objective is underspecified:

DefaultForwardingObjective{id=763963335, op=ADD, priority=40000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:lldp]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=true, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=1, name=org.onosproject.core}, permanent=true,
timeout=0}

2019-03-19T13:42:55.784723374Z 2019-03-19 13:42:55,784 | WARN | tive-
installer-3 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=1156990345,

op=ADD, priority=40000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:eapol]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=true, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=1, name=org.onosproject.core}, permanent=true,
timeout=0}. Reason = BADPARAMS

2019-03-19T13:42:55.7849893Z 2019-03-19 13:42:55,784 | WARN | tive-
installer-2 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=-2062265795,

op=ADD, priority=40000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:bddp]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=true, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=1, name=org.onosproject.core}, permanent=true,
timeout=0}. Reason = BADPARAMS

2019-03-19T13:42:55.785004358Z 2019-03-19 13:42:55,784 | WARN | tive-
installer-1 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=763963335,

op=ADD, priority=40000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:lldp]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER],
deferred=[], transition=None, meter=[], cleared=true, StatTrigger=null,
metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=1, name=org.onosproject.core}, permanent=true,
timeout=0}. Reason = BADPARAMS

2019-03-19T13:42:55.785173908Z 2019-03-19 13:42:55,784 | WARN | tive-installer-3 | PacketManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Failed to install packet request
DefaultPacketRequest{selector=DefaultTrafficSelector{criteria=[ETH_TYPE:eapol]}, priority=40000, appld=DefaultApplicationId{id=171, name=org.opencord.aaa}, nodeId=10.233.75.15, applies to=all} to of:00000000ac014ce: BADPARAMS

2019-03-19T13:42:55.785291911Z 2019-03-19 13:42:55,785 | WARN | tive-installer-2 | PacketManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Failed to install packet request
DefaultPacketRequest{selector=DefaultTrafficSelector{criteria=[ETH_TYPE:bddp]}, priority=40000, appld=DefaultApplicationId{id=176, name=org.onosproject.provider.lldp}, nodeId=10.233.75.15, applies to=all} to of:00000000ac014ce: BADPARAMS

2019-03-19T13:42:55.785499396Z 2019-03-19 13:42:55,785 | WARN | tive-installer-1 | PacketManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Failed to install packet request
DefaultPacketRequest{selector=DefaultTrafficSelector{criteria=[ETH_TYPE:lldp]}, priority=40000, appld=DefaultApplicationId{id=176, name=org.onosproject.provider.lldp}, nodeId=10.233.75.15, applies to=all} to of:00000000ac014ce: BADPARAMS

2019-03-19T13:42:55.797658125Z 2019-03-19 13:42:55,797 | INFO | ce-operations-19 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | LLDP filter for device of:00000000ac014ce on port 65536 installed.

2019-03-19T13:42:55.79792088Z 2019-03-19 13:42:55,797 | WARN | tive-installer-0 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | OLT can only filter DHCP, wrong UDP Src or Dst Port

2019-03-19T13:42:55.798105202Z 2019-03-19 13:42:55,797 | WARN | tive-installer-0 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultFilteringObjective{id=-748226364, type=PERMIT, op=ADD, priority=10000, key=IN_PORT:65536, conditions=[ETH_TYPE:ipv4, IP_PROTO:17, UDP_SRC:67, UDP_DST:68], meta=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, appld=DefaultApplicationId{id=177, name=org.opencord.olt}, permanent=true, timeout=0}. Reason = UNSUPPORTED

2019-03-19T13:42:55.798466911Z 2019-03-19 13:42:55,798 | INFO | tive-installer-0 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | DHCP v4 filter for device of:00000000ac014ce on port 65536 failed installation because UNSUPPORTED

2019-03-19T13:42:55.798495094Z 2019-03-19 13:42:55,798 | WARN | tive-installer-3 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 |

2019-03-19T13:42:55.798503935Z Only the following are Supported in OLT for filter ->

2019-03-19T13:42:55.798510961Z ETH TYPE : EAPOL, LLDP and IPV4

2019-03-19T13:42:55.798516862Z IPV4 TYPE: IGMP and UDP (for DHCP)

2019-03-19T13:42:55.798652547Z 2019-03-19 13:42:55,798 | WARN | tive-installer-3 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultFilteringObjective{id=1412147047, type=PERMIT, op=ADD, priority=10000, key=IN_PORT:65536, conditions=[ETH_TYPE:ipv6, IP_PROTO:17, UDP_SRC:546, UDP_DST:547], meta=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, appld=DefaultApplicationId{id=177, name=org.opencord.olt}, permanent=true, timeout=0}. Reason = UNSUPPORTED

2019-03-19T13:42:55.798790975Z 2019-03-19 13:42:55,798 | INFO | tive-installer-3 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | DHCP v6 filter for device of:000000000ac014ce on port 65536 failed installation because UNSUPPORTED

2019-03-19T13:42:55.805436482Z 2019-03-19 13:42:55,805 | INFO | ce-operations-27 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | DHCP v4 filter for device of:000000000ac014ce on port 65536 installed.

2019-03-19T13:42:55.972110352Z 2019-03-19 13:42:55,971 | INFO | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** LINK ADDED DefaultLink{src=of:000000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false}

2019-03-19T13:42:55.972154908Z 2019-03-19 13:42:55,971 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Could not check validity of link DefaultLink{src=of:000000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false} as subtending devices are not yet configured

2019-03-19T13:42:55.972163789Z 2019-03-19 13:42:55,972 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | processLinkAdded: Link Added notification without Device Added event, still handling it

2019-03-19T13:42:55.972194035Z 2019-03-19 13:42:55,972 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** DEVICE ADDED with ID of:000000000ac014ce

2019-03-19T13:42:55.972343217Z 2019-03-19 13:42:55,972 | WARN | sr-event-main-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | getRouterIpv4 fails for device: of:000000000ac014ce. Aborting populatelpPunts.

2019-03-19T13:42:55.973173716Z 2019-03-19 13:42:55,972 | ERROR | tive-

installer-2 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=34647077, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:arp]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}
2019-03-19T13:42:55.973199239Z 2019-03-19 13:42:55,972 | WARN | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Device configuration unavailable. Device of: 00000000ac014ce will be processed after configuration.
2019-03-19T13:42:55.973206682Z 2019-03-19 13:42:55,972 | ERROR | tive-installer-0 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=590874280, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:133]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}
2019-03-19T13:42:55.973218058Z 2019-03-19 13:42:55,972 | ERROR | tive-installer-3 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=1270932650, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:135]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}
2019-03-19T13:42:55.973361369Z 2019-03-19 13:42:55,973 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Source device of this link is not configured.. not processing further
2019-03-19T13:42:55.973371338Z 2019-03-19 13:42:55,972 | ERROR | tive-installer-1 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=-1216580183, op=ADD, priority=30000,

selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:134]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}
2019-03-19T13:42:55.973590812Z 2019-03-19 13:42:55,973 | WARN | tive-installer-2 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=34647077, op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:arp]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.973603058Z 2019-03-19 13:42:55,973 | WARN | tive-installer-3 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=1270932650, op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:135]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.973612057Z 2019-03-19 13:42:55,973 | WARN | tive-installer-1 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=-1216580183, op=ADD, priority=30000,
selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:134]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.973783729Z 2019-03-19 13:42:55,973 | WARN | tive-installer-0 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=590874280, op=ADD, priority=30000,

selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:133]},
treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE,
appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.97388952Z 2019-03-19 13:42:55,973 | WARN | tive-installer-2 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt ARP to of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.973897943Z 2019-03-19 13:42:55,973 | WARN | tive-installer-1 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.973981373Z 2019-03-19 13:42:55,973 | WARN | tive-installer-3 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.973989269Z 2019-03-19 13:42:55,973 | WARN | tive-installer-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.974201046Z 2019-03-19 13:42:55,973 | ERROR | tive-installer-2 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 | Forwarding objective is underspecified:
DefaultForwardingObjective{id=-536521813, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:136]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE, appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}
2019-03-19T13:42:55.974385536Z 2019-03-19 13:42:55,974 | WARN | tive-installer-2 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultForwardingObjective{id=-536521813, op=ADD, priority=30000, selector=DefaultTrafficSelector{criteria=[ETH_TYPE:ipv6, IP_PROTO:58, ICMPV6_TYPE:136]}, treatment=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, nextId=null, meta=null, flag=VERSATILE,

appId=DefaultApplicationId{id=16, name=org.onosproject.segmentrouting}, permanent=true, timeout=0}. Reason = BADPARAMS
2019-03-19T13:42:55.974502097Z 2019-03-19 13:42:55,974 | WARN | tive-installer-2 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Failed to install forwarding objective to punt NDP to of:000000000ac014ce: BADPARAMS
2019-03-19T13:42:55.985173821Z 2019-03-19 13:42:55,984 | INFO | nos-topo-build-7 | TopologyManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Topology DefaultTopology{time=2135770224337257, creationTime=1553002975981, computeCost=441772, clusters=2, devices=2, links=1} changed
2019-03-19T13:42:55.985449963Z 2019-03-19 13:42:55,985 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Processing topology event TOPOLOGY_CHANGED, topology age 2135770224337257, reasons 1
2019-03-19T13:42:55.98561211Z 2019-03-19 13:42:55,985 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Could not check validity of link DefaultLink{src=of:000000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false} as subtending devices are not yet configured
2019-03-19T13:42:55.98564068Z 2019-03-19 13:42:55,985 | WARN | sr-event-main-0 | TopologyHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Source device of this link is not configured.. not processing further
2019-03-19T13:42:56.879212855Z 2019-03-19 13:42:56,878 | INFO | f-event-stats-17 | DistributedGroupStore | 132 - org.onosproject.onos-core-dist - 1.13.5 | Group AUDIT: Setting device of:000000000ac014ce initial AUDIT completed
2019-03-19T13:43:04.834478335Z 2019-03-19 13:43:04,833 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received port status message from 00:00:00:00:0a:c0:14:ce/16: OFPortStatusVer13(xid=2, reason=ADD, desc=OFPortDescVer13(portNo=16, hwAddr=08:00:00:00:00:10, name=ALPHe3d1cfa7, config=[], state=[LINK_DOWN], curr=[PF_10GB_FD, PF_FIBER], advertised=[PF_10GB_FD, PF_FIBER], supported=[], peer=[PF_10GB_FD, PF_FIBER], currSpeed=64, maxSpeed=64))
2019-03-19T13:43:04.835411652Z 2019-03-19 13:43:04,835 | INFO | onos-of-worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:000000000ac014ce port 16 status changed
2019-03-19T13:43:04.836603975Z 2019-03-19 13:43:04,836 | INFO | ispatch-default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 | Got AccessDeviceEvent: UNI_ADDED
2019-03-19T13:43:05.953423369Z 2019-03-19 13:43:05,952 | INFO | onos-of-

worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received port status message from 00:00:00:00:0a:c0:14:ce/16: OFPortStatusVer13(xid=3, reason=MODIFY, desc=OFPortDescVer13(portNo=16, hwAddr=08:00:00:00:00:10, name=ALPHe3d1cfa7, config=[], state=[LIVE], curr=[PF_10GB_FD, PF_FIBER], advertised=[PF_10GB_FD, PF_FIBER], supported=[], peer=[PF_10GB_FD, PF_FIBER], currSpeed=64, maxSpeed=64))
2019-03-19T13:43:05.954158126Z 2019-03-19 13:43:05,953 | INFO | onos-of-worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:00000000ac014ce port 16 status changed
2019-03-19T13:43:05.955154843Z 2019-03-19 13:43:05,954 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:00000000ac014ce, type=SWITCH, manufacturer=VOLTHA Project, hwVersion=, swVersion=, serialNumber=EC1838000853, driver=voltha}/DefaultPort{element=of:00000000ac014ce, number=16, isEnabled=true, type=FIBER, portSpeed=0, annotations={adminState=enabled, portName=ALPHe3d1cfa7, portMac=08:00:00:00:00:10}} -> PORT_UPDATED
2019-03-19T13:43:05.9551893Z 2019-03-19 13:43:05,954 | INFO | ispatch-default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 | Got AccessDeviceEvent: UNI_ADDED
2019-03-19T13:43:05.9551993Z 2019-03-19 13:43:05,954 | WARN | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Device configuration uploading. Not handling port event fordev: of:00000000ac014ce port: 16
2019-03-19T13:43:05.965386631Z 2019-03-19 13:43:05,964 | INFO | ice-operations-1 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | Eapol filter for of:00000000ac014ce on 16 installed.
2019-03-19T13:43:21.956942395Z 2019-03-19 13:43:21,956 | INFO | .233.75.22:41442 | StateMachine | 187 - org.opencord.aaa - 1.8.0.SNAPSHOT | Creating a new state machine for of:00000000ac014ce16
2019-03-19T13:43:21.9569771Z 2019-03-19 13:43:21,956 | INFO | .233.75.22:41442 | StateMachine\$Idle | 187 - org.opencord.aaa - 1.8.0.SNAPSHOT | Moving from IDLE state to STARTED state.
2019-03-19T13:43:21.957097981Z 2019-03-19 13:43:21,956 | INFO | .233.75.22:41442 | AaaManager | 187 - org.opencord.aaa - 1.8.0.SNAPSHOT | Auth event STARTED for of:00000000ac014ce/16
2019-03-19T13:43:21.957218274Z 2019-03-19 13:43:21,957 | INFO | .233.75.22:41442 | StateMachine | 187 - org.opencord.aaa - 1.8.0.SNAPSHOT | Current State 1
2019-03-19T13:43:22.104004974Z 2019-03-19 13:43:22,103 | INFO | .233.75.22:41442 | StateMachine\$Started | 187 - org.opencord.aaa - 1.8.0.SNAPSHOT | Moving from STARTED state to PENDING state.

2019-03-19T13:43:22.104037247Z 2019-03-19 13:43:22,103 | INFO | .
233.75.22:41442 | AaaManager | 187 - org.opencord.aaa -
1.8.0.SNAPSHOT | Auth event REQUESTED for of:000000000ac014ce/16
2019-03-19T13:43:22.104046498Z 2019-03-19 13:43:22,103 | INFO | .
233.75.22:41442 | StateMachine | 187 - org.opencord.aaa -
1.8.0.SNAPSHOT | Current State 2
2019-03-19T13:43:22.188961351Z 2019-03-19 13:43:22,188 | INFO | AAA-
radius-0 | AaaManager | 187 - org.opencord.aaa -
1.8.0.SNAPSHOT | Send EAP success message to supplicant B4:96:91:0C:4F:E5
2019-03-19T13:43:22.189009454Z 2019-03-19 13:43:22,188 | INFO | AAA-
radius-0 | StateMachine\$Pending | 187 - org.opencord.aaa -
1.8.0.SNAPSHOT | Moving from PENDING state to AUTHORIZED state.
2019-03-19T13:43:22.189160188Z 2019-03-19 13:43:22,188 | INFO | AAA-
radius-0 | StateMachine | 187 - org.opencord.aaa -
1.8.0.SNAPSHOT | Current State 3
2019-03-19T13:43:22.189253206Z 2019-03-19 13:43:22,189 | INFO | AAA-
radius-0 | AaaManager | 187 - org.opencord.aaa -
1.8.0.SNAPSHOT | Auth event APPROVED for of:000000000ac014ce/16
2019-03-19T13:43:46.440995201Z 2019-03-19 13:43:46,440 | INFO |
qtp2119703484-54 | Olt | 186 - org.opencord.olt-app -
2.1.0.SNAPSHOT | Programming vlans for subscriber: [id:ALPHe3d1cfa7,cTag:
999,sTag:111,nasPortId:PON
1/1/03/1:1.1.1,uplinkPort:-1,slot:-1,hardwareIdentifier:null,ipaddress:null,nasId:null,c
ircuitId:foo1,remoteld:bar1]
2019-03-19T13:43:46.444013499Z 2019-03-19 13:43:46,443 | INFO | ispatch-
default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 |
Got AccessDeviceEvent: SUBSCRIBER_REGISTERED
2019-03-19T13:43:46.460627618Z 2019-03-19 13:43:46,460 | INFO | ice-
operations-5 | Olt | 186 - org.opencord.olt-app -
2.1.0.SNAPSHOT | DHCP v4 filter for device of:000000000ac014ce on port 16
installed.
2019-03-19T13:43:46.460654349Z 2019-03-19 13:43:46,460 | WARN | tive-
installer-1 | OltPipeline | 170 - org.onosproject.onos-drivers-default -
1.13.5 |
2019-03-19T13:43:46.460662864Z Only the following are Supported in OLT for
filter ->
2019-03-19T13:43:46.460669734Z ETH TYPE : EAPOL, LLDP and IPV4
2019-03-19T13:43:46.460675783Z IPV4 TYPE: IGMP and UDP (for DHCP)
2019-03-19T13:43:46.461145906Z 2019-03-19 13:43:46,460 | WARN | tive-
installer-1 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-
net - 1.13.5 | Flow objective onError DefaultFilteringObjective{id=-905210887,
type=PERMIT, op=ADD, priority=10000, key=IN_PORT:16,
conditions=[ETH_TYPE:ipv6, IP_PROTO:17, UDP_SRC:547, UDP_DST:546]},

meta=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[], transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null}, appId=DefaultApplicationId{id=177, name=org.opencord.olt}, permanent=true, timeout=0}. Reason = UNSUPPORTED

2019-03-19T13:43:46.461173678Z 2019-03-19 13:43:46,461 | INFO | tive-installer-1 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | DHCP v6 filter for device of:000000000ac014ce on port 16 failed installation because UNSUPPORTED

2019-03-19T13:43:48.922168382Z 2019-03-19 13:43:48,921 | INFO | qtp2119703484-56 | XconnectManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Adding or updating xconnect. deviceId=of:0000cc37ab5b6da8, vlanId=111, ports=[7, 8]

2019-03-19T13:43:49.820769875Z 2019-03-19 13:43:49,820 | INFO | .233.75.22:41442 | DhcpL2Relay | 188 - org.opencord.dhctl2relay - 1.5.0.SNAPSHOT | Received DHCP Packet of type DHCPDISCOVER from of:000000000ac014ce/16

2019-03-19T13:43:49.822056573Z 2019-03-19 13:43:49,821 | INFO | .233.75.22:41442 | DhcpL2Relay | 188 - org.opencord.dhctl2relay - 1.5.0.SNAPSHOT | Finished processing packet.. relaying to dhcpServer

2019-03-19T13:43:49.825843853Z 2019-03-19 13:43:49,825 | INFO | sr-event-host-0 | HostHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Host B4:96:91:0C:4F:E5/4091 is added at [of:000000000ac014ce/16]

2019-03-19T13:43:49.825880814Z 2019-03-19 13:43:49,825 | WARN | ect-host-event-0 | XconnectManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Unsupported host event type: HOST_ADDED received. Ignoring.

2019-03-19T13:43:49.825891148Z 2019-03-19 13:43:49,825 | INFO | sr-event-host-0 | HostHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Populating bridging entry for host B4:96:91:0C:4F:E5/4091 at of:000000000ac014ce:16

2019-03-19T13:43:49.826518543Z 2019-03-19 13:43:49,826 | WARN | sr-event-host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Tagged host B4:96:91:0C:4F:E5/4091 is not allowed on of:000000000ac014ce/16 without VLAN listed in tagged vlan

2019-03-19T13:43:49.826548924Z 2019-03-19 13:43:49,826 | WARN | sr-event-host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Fail to build fwd obj for host B4:96:91:0C:4F:E5/4091. Abort.

2019-03-19T13:43:50.826147462Z 2019-03-19 13:43:50,825 | INFO | 33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhctl2relay - 1.5.0.SNAPSHOT | Received DHCP Packet of type DHCP OFFER from of:0000cc37ab5b6da8/8

2019-03-19T13:43:50.828415411Z 2019-03-19 13:43:50,828 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Finished processing packet.. relaying to client
2019-03-19T13:43:50.832457189Z 2019-03-19 13:43:50,829 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Sending DHCP packet to client at of:000000000ac014ce/16
2019-03-19T13:43:56.388906706Z 2019-03-19 13:43:56,388 | INFO | .
233.75.22:41442 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Received DHCP Packet of type DHCPDISCOVER from of:
000000000ac014ce/16
2019-03-19T13:43:56.389803679Z 2019-03-19 13:43:56,389 | INFO | .
233.75.22:41442 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Finished processing packet.. relaying to dhcpServer
2019-03-19T13:43:56.392316487Z 2019-03-19 13:43:56,391 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Received DHCP Packet of type DHCP OFFER from of:
0000cc37ab5b6da8/8
2019-03-19T13:43:56.393551827Z 2019-03-19 13:43:56,393 | WARN | ect-host-
event-0 | XconnectManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Unsupported host event type: HOST_ADDED
received. Ignoring.
2019-03-19T13:43:56.393578978Z 2019-03-19 13:43:56,393 | INFO | sr-event-
host-0 | HostHandler | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Host B4:96:91:0C:4F:E5/999 is added at [of:
000000000ac014ce/16]
2019-03-19T13:43:56.393906784Z 2019-03-19 13:43:56,393 | INFO | sr-event-
host-0 | HostHandler | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Populating bridging entry for host B4:96:91:0C:
4F:E5/999 at of:000000000ac014ce:16
2019-03-19T13:43:56.394157658Z 2019-03-19 13:43:56,393 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Finished processing packet.. relaying to client
2019-03-19T13:43:56.394203519Z 2019-03-19 13:43:56,393 | WARN | sr-event-
host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Tagged host B4:96:91:0C:4F:E5/999 is not allowed
on of:000000000ac014ce/16 without VLAN listed in tagged vlan
2019-03-19T13:43:56.394373145Z 2019-03-19 13:43:56,394 | WARN | sr-event-
host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Fail to build fwd obj for host B4:96:91:0C:
4F:E5/999. Abort.
2019-03-19T13:43:56.395082551Z 2019-03-19 13:43:56,394 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Sending DHCP packet to client at of:000000000ac014ce/16

2019-03-19T13:43:56.502284837Z 2019-03-19 13:43:56,501 | INFO | .
233.75.22:41442 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Received DHCP Packet of type DHCPREQUEST from of:
00000000ac014ce/16

2019-03-19T13:43:56.502814903Z 2019-03-19 13:43:56,502 | INFO | .
233.75.22:41442 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Finished processing packet.. relaying to dhcpServer

2019-03-19T13:43:56.539198464Z 2019-03-19 13:43:56,538 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Received DHCP Packet of type DHCPACK from of:
0000cc37ab5b6da8/8

2019-03-19T13:43:56.55869495Z 2019-03-19 13:43:56,558 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Finished processing packet.. relaying to client

2019-03-19T13:43:56.559531356Z 2019-03-19 13:43:56,559 | INFO |
33.102.128:40728 | DhcpL2Relay | 188 - org.opencord.dhcpl2relay -
1.5.0.SNAPSHOT | Sending DHCP packet to client at of:00000000ac014ce/16

2019-03-19T13:43:56.560386366Z 2019-03-19 13:43:56,560 | WARN | ect-
host-event-0 | XconnectManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Unsupported host event type: HOST_UPDATED
received. Ignoring.

2019-03-19T13:43:56.560413841Z 2019-03-19 13:43:56,560 | INFO | sr-event-
host-0 | HostHandler | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Host B4:96:91:0C:4F:E5/999 is updated

2019-03-19T13:43:56.560705858Z 2019-03-19 13:43:56,560 | INFO | sr-event-
host-0 | HostHandler | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | 10.8.2.103 is not included in the subnet config of of:
00000000ac014ce/16. Ignored.

2019-03-19T13:44:06.309397657Z 2019-03-19 13:44:06,308 | INFO |
qtp2119703484-56 | XconnectManager | 177 - org.onosproject.onos-
apps-segmentrouting-app - 1.13.5 | Adding or updating xconnect. deviceId=of:
0000cc37ab5b6da8, vlanId=111, ports=[7, 8]

2019-03-19T13:44:15.593455979Z 2019-03-19 13:44:15,592 | INFO | onos-of-
worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-
openflow-ctl - 1.13.5 | Received port status message from
00:00:00:00:0a:c0:14:ce/16: OFPortStatusVer13(xid=10, reason=MODIFY,
desc=OFPortDescVer13(portNo=16, hwAddr=08:00:00:00:00:10,
name=ALPHe3d1cfa7, config=[], state=[LINK_DOWN], curr=[PF_10GB_FD,
PF_FIBER], advertised=[PF_10GB_FD, PF_FIBER], supported=[], peer=[PF_10GB_FD,
PF_FIBER], currSpeed=64, maxSpeed=64))

2019-03-19T13:44:15.594777369Z 2019-03-19 13:44:15,594 | INFO | onos-of-
worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net -
1.13.5 | Device of:00000000ac014ce port 16 status changed

2019-03-19T13:44:15.595532153Z 2019-03-19 13:44:15,595 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:00000000ac014ce, type=SWITCH, manufacturer=VOLTHA Project, hwVersion=, swVersion=, serialNumber=EC1838000853, driver=voltha}/DefaultPort{element=of:00000000ac014ce, number=16, isEnabled=false, type=FIBER, portSpeed=0, annotations={adminState=enabled, portName=ALPHe3d1cfa7, portMac=08:00:00:00:00:10}} -> PORT_UPDATED

2019-03-19T13:44:15.595565899Z 2019-03-19 13:44:15,595 | WARN | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Device configuration uploading. Not handling port event fordev: of:00000000ac014ce port: 16

2019-03-19T13:44:15.595836639Z 2019-03-19 13:44:15,595 | INFO | ispatch-default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 | Got AccessDeviceEvent: UNI_REMOVED

2019-03-19T13:44:15.600040742Z 2019-03-19 13:44:15,599 | WARN | ect-host-event-0 | XconnectManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Unsupported host event type: HOST_REMOVED received. Ignoring.

2019-03-19T13:44:15.600056235Z 2019-03-19 13:44:15,599 | INFO | sr-event-host-0 | HostHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Host B4:96:91:0C:4F:E5/999 is removed from [of:00000000ac014ce/16]

2019-03-19T13:44:15.600063887Z 2019-03-19 13:44:15,599 | INFO | sr-event-host-0 | HostHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Revoking bridging entry for host B4:96:91:0C:4F:E5/999 at of:00000000ac014ce:16

2019-03-19T13:44:15.600575352Z 2019-03-19 13:44:15,600 | WARN | sr-event-host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Tagged host B4:96:91:0C:4F:E5/999 is not allowed on of:00000000ac014ce/16 without VLAN listed in tagged vlan

2019-03-19T13:44:15.600610311Z 2019-03-19 13:44:15,600 | WARN | sr-event-host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Fail to build fwd obj for host B4:96:91:0C:4F:E5/999. Abort.

2019-03-19T13:44:15.600825126Z 2019-03-19 13:44:15,600 | INFO | sr-event-host-0 | HostHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | 10.8.2.103 is not included in the subnet config of of:00000000ac014ce/16. Ignored.

2019-03-19T13:44:15.601857877Z 2019-03-19 13:44:15,601 | WARN | ect-host-event-0 | XconnectManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Unsupported host event type: HOST_REMOVED received. Ignoring.

2019-03-19T13:44:15.605417469Z 2019-03-19 13:44:15,605 | INFO | ice-operations-3 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | Eapol filter for of:000000000ac014ce on 16 removed.

2019-03-19T13:44:15.606325474Z 2019-03-19 13:44:15,605 | INFO | sr-event-host-0 | HostHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Host B4:96:91:0C:4F:E5/4091 is removed from [of:000000000ac014ce/16]

2019-03-19T13:44:15.606358546Z 2019-03-19 13:44:15,606 | INFO | sr-event-host-0 | HostHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Revoking bridging entry for host B4:96:91:0C:4F:E5/4091 at of:000000000ac014ce:16

2019-03-19T13:44:15.606809655Z 2019-03-19 13:44:15,606 | WARN | sr-event-host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Tagged host B4:96:91:0C:4F:E5/4091 is not allowed on of:000000000ac014ce/16 without VLAN listed in tagged vlan

2019-03-19T13:44:15.606837409Z 2019-03-19 13:44:15,606 | WARN | sr-event-host-0 | RoutingRulePopulator | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Fail to build fwd obj for host B4:96:91:0C:4F:E5/4091. Abort.

2019-03-19T13:44:16.142526473Z 2019-03-19 13:44:16,142 | INFO | qtp2119703484-57 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | Removing programmed vlans for subscriber: [id:ALPHe3d1cfa7,cTag:999,sTag:111,nasPortId:PON 1/1/03/1:1.1.1,uplinkPort:-1,slot:-1,hardwareIdentifier:null,ipaddress:null,nasId:null,circuitId:foo1,remoteld:bar1]

2019-03-19T13:44:16.14563631Z 2019-03-19 13:44:16,145 | INFO | ispatch-default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 | Got AccessDeviceEvent: SUBSCRIBER_UNREGISTERED

2019-03-19T13:44:16.161836568Z 2019-03-19 13:44:16,161 | INFO | ce-operations-23 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | DHCP v4 filter for device of:000000000ac014ce on port 16 removed.

2019-03-19T13:44:16.161866415Z 2019-03-19 13:44:16,161 | WARN | tive-installer-3 | OltPipeline | 170 - org.onosproject.onos-drivers-default - 1.13.5 |

2019-03-19T13:44:16.161874801Z Only the following are Supported in OLT for filter ->

2019-03-19T13:44:16.161882028Z ETH TYPE : EAPOL, LLDP and IPV4

2019-03-19T13:44:16.161888684Z IPV4 TYPE: IGMP and UDP (for DHCP)

2019-03-19T13:44:16.162303031Z 2019-03-19 13:44:16,161 | WARN | tive-installer-3 | InOrderFlowObjectiveManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Flow objective onError DefaultFilteringObjective{id=-868200347, type=DENY, op=ADD, priority=10000, key=IN_PORT:16,

conditions=[ETH_TYPE:ipv6, IP_PROTO:17, UDP_SRC:547, UDP_DST:546],
meta=DefaultTrafficTreatment{immediate=[OUTPUT:CONTROLLER], deferred=[],
transition=None, meter=[], cleared=false, StatTrigger=null, metadata=null},
appId=DefaultApplicationId{id=177, name=org.opencord.olt}, permanent=true,
timeout=0}. Reason = UNSUPPORTED
2019-03-19T13:44:16.162336069Z 2019-03-19 13:44:16,162 | INFO | tive-
installer-3 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT |
DHCP v6 filter for device of:000000000ac014ce on port 16 failed removal
because UNSUPPORTED
2019-03-19T13:44:16.878949263Z 2019-03-19 13:44:16,878 | INFO |
qtp2119703484-55 | XconnectManager | 177 - org.onosproject.onos-
apps-segmentrouting-app - 1.13.5 | Adding or updating xconnect. deviceId=of:
0000cc37ab5b6da8, vlanId=111, ports=[7, 8]
2019-03-19T13:44:22.160910135Z 2019-03-19 13:44:22,160 | INFO |
qtp2119703484-55 | XconnectManager | 177 - org.onosproject.onos-
apps-segmentrouting-app - 1.13.5 | Removing xconnect. deviceId=of:
0000cc37ab5b6da8, vlanId=111
2019-03-19T13:45:26.713441919Z 2019-03-19 13:45:26,712 | INFO | onos-of-
worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-
openflow-ctl - 1.13.5 | Received port status message from
00:00:00:00:0a:c0:14:ce/16: OFPortStatusVer13(xid=17, reason=MODIFY,
desc=OFPortDescVer13(portNo=16, hwAddr=08:00:00:00:00:10,
name=ALPHe3d1cfa7, config=[], state=[LIVE], curr=[PF_10GB_FD, PF_FIBER],
advertised=[PF_10GB_FD, PF_FIBER], supported=[], peer=[PF_10GB_FD, PF_FIBER],
currSpeed=64, maxSpeed=64))
2019-03-19T13:45:26.715043986Z 2019-03-19 13:45:26,714 | INFO | onos-of-
worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net -
1.13.5 | Device of:000000000ac014ce port 16 status changed
2019-03-19T13:45:26.716029974Z 2019-03-19 13:45:26,715 | INFO | sr-event-
main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:
000000000ac014ce, type=SWITCH, manufacturer=VOLTHA Project, hwVersion=,
swVersion=, serialNumber=EC1838000853, driver=voltha}/
DefaultPort{element=of:000000000ac014ce, number=16, isEnabled=true,
type=FIBER, portSpeed=0, annotations={adminState=enabled,
portName=ALPHe3d1cfa7, portMac=08:00:00:00:00:10}} -> PORT_UPDATED
2019-03-19T13:45:26.716039361Z 2019-03-19 13:45:26,715 | WARN | sr-event-
main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Device configuration uploading. Not handling port
event fordev: of:000000000ac014ce port: 16
2019-03-19T13:45:26.716807354Z 2019-03-19 13:45:26,716 | INFO | ispatch-
default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 |
Got AccessDeviceEvent: UNI_ADDED

2019-03-19T13:45:26.727056531Z 2019-03-19 13:45:26,726 | INFO | ice-operations-1 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | Eapol filter for of:000000000ac014ce on 16 installed.

2019-03-19T13:48:10.572547073Z 2019-03-19 13:48:10,571 | INFO |]-nio2-thread-35 | ServerSession | 30 - org.apache.sshd.core - 0.14.0 | Server session created from /10.233.102.128:39030

2019-03-19T13:48:10.753443503Z 2019-03-19 13:48:10,752 | INFO |]-nio2-thread-43 | ServerUserAuthService | 30 - org.apache.sshd.core - 0.14.0 | Session karaf@/10.233.102.128:39030 authenticated

2019-03-19T13:48:11.76895937Z 2019-03-19 13:48:11,768 | INFO | 8]-nio2-thread-4 | ServerSession | 30 - org.apache.sshd.core - 0.14.0 | Server session created from /10.233.102.128:39068

2019-03-19T13:48:11.9479328Z 2019-03-19 13:48:11,947 | INFO |]-nio2-thread-12 | ServerUserAuthService | 30 - org.apache.sshd.core - 0.14.0 | Session karaf@/10.233.102.128:39068 authenticated

2019-03-19T13:48:12.931149807Z 2019-03-19 13:48:12,930 | INFO |]-nio2-thread-31 | ServerSession | 30 - org.apache.sshd.core - 0.14.0 | Server session created from /10.233.102.128:39088

2019-03-19T13:48:13.105318979Z 2019-03-19 13:48:13,104 | INFO |]-nio2-thread-39 | ServerUserAuthService | 30 - org.apache.sshd.core - 0.14.0 | Session karaf@/10.233.102.128:39088 authenticated

2019-03-19T13:48:14.04828303Z 2019-03-19 13:48:14,047 | INFO |]-nio2-thread-40 | ServerSession | 30 - org.apache.sshd.core - 0.14.0 | Server session created from /10.233.102.128:39114

2019-03-19T13:48:14.238307223Z 2019-03-19 13:48:14,237 | INFO |]-nio2-thread-48 | ServerUserAuthService | 30 - org.apache.sshd.core - 0.14.0 | Session karaf@/10.233.102.128:39114 authenticated

2019-03-19T13:48:32.711069317Z 2019-03-19 13:48:32,710 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received port status message from 00:00:00:00:0a:c0:14:ce/16: OFPortStatusVer13(xid=18, reason=MODIFY, desc=OFPortDescVer13(portNo=16, hwAddr=08:00:00:00:00:10, name=ALPHe3d1cfa7, config=[], state=[LINK_DOWN], curr=[PF_10GB_FD, PF_FIBER], advertised=[PF_10GB_FD, PF_FIBER], supported=[], peer=[PF_10GB_FD, PF_FIBER], currSpeed=64, maxSpeed=64))

2019-03-19T13:48:32.712241026Z 2019-03-19 13:48:32,711 | INFO | onos-of-worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:000000000ac014ce port 16 status changed

2019-03-19T13:48:32.713118617Z 2019-03-19 13:48:32,712 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:000000000ac014ce, type=SWITCH, manufacturer=VOLTHA Project, hwVersion=, swVersion=, serialNumber=EC1838000853, driver=voltha}/

DefaultPort{element=of:000000000ac014ce, number=16, isEnabled=false, type=FIBER, portSpeed=0, annotations={adminState=enabled, portName=ALPHe3d1cfa7, portMac=08:00:00:00:00:10}} -> PORT_UPDATED 2019-03-19T13:48:32.713149072Z 2019-03-19 13:48:32,712 | WARN | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Device configuration uploading. Not handling port event fordev: of:000000000ac014ce port: 16
2019-03-19T13:48:32.71407156Z 2019-03-19 13:48:32,713 | INFO | ispatch-default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 | Got AccessDeviceEvent: UNI_REMOVED
2019-03-19T13:48:32.726260301Z 2019-03-19 13:48:32,725 | INFO | ce-operations-31 | Olt | 186 - org.opencord.olt-app - 2.1.0.SNAPSHOT | Eapol filter for of:000000000ac014ce on 16 removed.
2019-03-19T13:48:42.884106909Z 2019-03-19 13:48:42,883 | INFO | onos-of-worker-0 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received port status message from 00:00:cc:37:ab:5b:6d:a8/7: OFPortStatusVer13(xid=0, reason=MODIFY, desc=OFPortDescVer13(portNo=7, hwAddr=cc:37:ab:5b:6d:a9, name=port7, config=[], state=[LINK_DOWN], curr=[PF_FIBER, PF_40GB_FD], advertised=[], supported=[PF_10MB_FD, PF_100MB_FD, PF_1GB_FD, PF_10GB_FD, PF_FIBER, PF_AUTONEG, PF_PAUSE, PF_PAUSE_ASYM, PF_40GB_FD, PF_OTHER], peer=[], currSpeed=40000000, maxSpeed=40000000))
2019-03-19T13:48:42.885040724Z 2019-03-19 13:48:42,884 | INFO | onos-of-worker-0 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:0000cc37ab5b6da8 port 7 status changed
2019-03-19T13:48:42.885455382Z 2019-03-19 13:48:42,885 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:0000cc37ab5b6da8, type=SWITCH, manufacturer=Accton Corp., hwVersion=x86-64-accton-as6712-32x-r0, swVersion=ofdpa 3.0.5.5+accton1.7-1, serialNumber=671232X1534021, driver=ofdpa3}/DefaultPort{element=of:0000cc37ab5b6da8, number=7, isEnabled=false, type=FIBER, portSpeed=40000, annotations={adminState=enabled, portName=port7, portMac=cc:37:ab:5b:6d:a9}} -> PORT_UPDATED
2019-03-19T13:48:42.885656873Z 2019-03-19 13:48:42,885 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Switchport of:0000cc37ab5b6da8/7 disabled..removing filters
2019-03-19T13:48:42.886497536Z 2019-03-19 13:48:42,886 | INFO | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** LINK REMOVED DefaultLink{src=of:000000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false}

2019-03-19T13:48:42.886752612Z 2019-03-19 13:48:42,886 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Could not check validity of link DefaultLink{src=of:00000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false} as subtending devices are not yet configured

2019-03-19T13:48:42.886799626Z 2019-03-19 13:48:42,886 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Unable to determine if link was the last uplinkisEdgeDevice fails for device: of:00000000ac014ce.

2019-03-19T13:48:42.887003949Z 2019-03-19 13:48:42,886 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Query for bidi-link down but reverse-link not found for link DefaultLink{src=of:00000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false}

2019-03-19T13:48:42.899883694Z 2019-03-19 13:48:42,899 | INFO | nos-topo-build-0 | TopologyManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Topology DefaultTopology{time=2136117138847270, creationTime=1553003322896, computeCost=713167, clusters=2, devices=2, links=0} changed

2019-03-19T13:48:42.900340832Z 2019-03-19 13:48:42,899 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Processing topology event TOPOLOGY_CHANGED, topology age 2136117138847270, reasons 1

2019-03-19T13:48:42.900603954Z 2019-03-19 13:48:42,900 | WARN | sr-event-main-0 | LinkHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Could not check validity of link DefaultLink{src=of:00000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false} as subtending devices are not yet configured

2019-03-19T13:48:42.900936489Z 2019-03-19 13:48:42,900 | INFO | sr-event-main-0 | TopologyHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Processing - Event: LinkEvent{time=2019-03-19T13:48:42.885Z, type=LINK_REMOVED, subject=DefaultLink{src=of:00000000ac014ce/65536, dst=of:0000cc37ab5b6da8/7, type=DIRECT, state=ACTIVE, expected=false}}

2019-03-19T13:48:43.344112636Z 2019-03-19 13:48:43,343 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Received port status message from 00:00:00:00:0a:c0:14:ce/65536: OFPortStatusVer13(xid=20, reason=MODIFY, desc=OFPortDescVer13(portNo=65536, hwAddr=00:00:00:01:00:00, name=nni-65536, config=[], state=[LINK_DOWN], curr=[PF_1GB_FD, PF_FIBER], advertised=[PF_1GB_FD, PF_FIBER], supported=[], peer=[PF_1GB_FD, PF_FIBER], currSpeed=32, maxSpeed=32))

2019-03-19T13:48:43.344775203Z 2019-03-19 13:48:43,344 | INFO | onos-of-

worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:000000000ac014ce port 65536 status changed
2019-03-19T13:48:43.345279381Z 2019-03-19 13:48:43,345 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** PORT UPDATED DefaultDevice{id=of:000000000ac014ce, type=SWITCH, manufacturer=VOLTHA Project, hwVersion=, swVersion=, serialNumber=EC1838000853, driver=voltha}/DefaultPort{element=of:000000000ac014ce, number=65536, isEnabled=false, type=FIBER, portSpeed=0, annotations={adminState=enabled, portName=nni-65536, portMac=00:00:00:01:00:00}} -> PORT_UPDATED
2019-03-19T13:48:43.345315446Z 2019-03-19 13:48:43,345 | WARN | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Device configuration uploading. Not handling port event for dev: of:000000000ac014ce port: 65536
2019-03-19T13:48:57.308149443Z 2019-03-19 13:48:57,307 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Switch disconnected callback for sw:DefaultSwitchHandshaker{session=10.233.75.22:41442, dpid=00:00:00:00:0a:c0:14:ce}. Cleaning up ...
2019-03-19T13:48:57.308191214Z 2019-03-19 13:48:57,307 | INFO | onos-of-worker-2 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | DefaultSwitchHandshaker{session=10.233.75.22:41442, dpid=00:00:00:00:0a:c0:14:ce}:removal called
2019-03-19T13:48:57.308327742Z 2019-03-19 13:48:57,308 | INFO | onos-of-worker-2 | PortStatsCollector | 165 - org.onosproject.onos-providers-openflow-device - 1.13.5 | Stopping Port Stats collection thread for 00:00:00:00:0a:c0:14:ce
2019-03-19T13:48:57.30851716Z 2019-03-19 13:48:57,308 | INFO | onos-of-worker-2 | DeviceManager | 130 - org.onosproject.onos-core-net - 1.13.5 | Device of:000000000ac014ce disconnected from this node
2019-03-19T13:48:57.314499568Z 2019-03-19 13:48:57,313 | INFO | sr-event-main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | ** DEVICE DOWN Processing device event DEVICE_AVAILABILITY_CHANGED for unavailable device of:000000000ac014ce
2019-03-19T13:48:57.314535195Z 2019-03-19 13:48:57,314 | INFO | ispatch-default0 | AccessDeviceKafkaIntegration | 189 - org.opencord.kafka - 1.0.0 | Got AccessDeviceEvent: DEVICE_DISCONNECTED
2019-03-19T13:48:57.315151457Z 2019-03-19 13:48:57,314 | INFO | sr-event-main-0 | DefaultRoutingHandler | 177 - org.onosproject.onos-apps-segmentrouting-app - 1.13.5 | Starting to populate routing rules from Topology change
2019-03-19T13:48:57.315552289Z 2019-03-19 13:48:57,315 | INFO | onos-of-worker-2 | MeterStatsCollector | 169 - org.onosproject.onos-providers-

openflow-meter - 1.13.5 | Stopping Meter Stats collection thread for
00:00:00:00:0a:c0:14:ce
2019-03-19T13:48:57.315981475Z 2019-03-19 13:48:57,315 | INFO | sr-event-
main-0 | DefaultRoutingHandler | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Hash-groups changed for link status change
2019-03-19T13:48:57.316930349Z 2019-03-19 13:48:57,316 | INFO | onos-of-
worker-2 | GroupStatsCollector | 168 - org.onosproject.onos-providers-
openflow-group - 1.13.5 | Stopping Group Stats collection thread for
00:00:00:00:0a:c0:14:ce
2019-03-19T13:48:57.316964098Z 2019-03-19 13:48:57,316 | INFO | sr-event-
main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | ** MASTERSHIP CHANGED Invalidating
shouldProgram cache for of:000000000ac014ce/pair=Optional.empty due to
change
2019-03-19T13:48:57.317302096Z 2019-03-19 13:48:57,316 | INFO | sr-event-
main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | ** MASTERSHIP CHANGED Invalidating
shouldProgram cache for of:000000000ac014ce/pair=Optional.empty due to
change
2019-03-19T13:48:57.321948178Z 2019-03-19 13:48:57,321 | INFO | nos-topo-
build-1 | TopologyManager | 130 - org.onosproject.onos-core-net -
1.13.5 | Topology DefaultTopology{time=2136131562830038,
creationTime=1553003337320, computeCost=121857, clusters=1, devices=1,
links=0} changed
2019-03-19T13:48:57.322280387Z 2019-03-19 13:48:57,321 | INFO | sr-event-
main-0 | SegmentRoutingManager | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Processing topology event TOPOLOGY_CHANGED,
topology age 2136131562830038, reasons 1
2019-03-19T13:48:57.322541255Z 2019-03-19 13:48:57,322 | INFO | sr-event-
main-0 | TopologyHandler | 177 - org.onosproject.onos-apps-
segmentrouting-app - 1.13.5 | Processing - Event:
DeviceEvent{time=2019-03-19T13:48:57.309Z,
type=DEVICE_AVAILABILITY_CHANGED, subject=DefaultDevice{id=of:
000000000ac014ce, type=SWITCH, manufacturer=VOLTHA Project, hwVersion=,
swVersion=, serialNumber=EC1838000853, driver=voltha}}
2019-03-19T13:49:00.464159155Z 2019-03-19 13:49:00,463 | WARN | pool-17-
thread-1 | OFChannelHandler | 164 - org.onosproject.onos-protocols-
openflow-ctl - 1.13.5 | Dropping messages for switch
DefaultSwitchHandshaker{session=10.233.75.22:41442,
dpid=00:00:00:00:0a:c0:14:ce} because channel is not connected:
[OFMeterStatsRequestVer13(xid=0, flags=[], meterId=-1)]
2019-03-19T13:49:00.464211778Z 2019-03-19 13:49:00,463 | WARN | pool-17-
thread-1 | DefaultSwitchHandshaker | 163 - org.onosproject.onos-protocols-

openflow-api - 1.13.5 | Dropping messages for switch 00:00:00:00:0a:c0:14:ce because channel is not connected: [OFMeterStatsRequestVer13(xid=0, flags=[], meterId=-1)]
2019-03-19T13:49:00.464382092Z 2019-03-19 13:49:00,464 | WARN | pool-17-thread-1 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Dropping messages for switch DefaultSwitchHandshaker{session=10.233.75.22:41442, dpid=00:00:00:00:0a:c0:14:ce} because channel is not connected: [OFGroupStatsRequestVer13(xid=371, flags=[], group=all)]
2019-03-19T13:49:00.464394966Z 2019-03-19 13:49:00,464 | WARN | pool-17-thread-1 | DefaultSwitchHandshaker | 163 - org.onosproject.onos-protocols-openflow-api - 1.13.5 | Dropping messages for switch 00:00:00:00:0a:c0:14:ce because channel is not connected: [OFGroupStatsRequestVer13(xid=371, flags=[], group=all)]
2019-03-19T13:49:00.464562887Z 2019-03-19 13:49:00,464 | WARN | pool-17-thread-1 | OFChannelHandler | 164 - org.onosproject.onos-protocols-openflow-ctl - 1.13.5 | Dropping messages for switch DefaultSwitchHandshaker{session=10.233.75.22:41442, dpid=00:00:00:00:0a:c0:14:ce} because channel is not connected: [OFGroupDescStatsRequestVer13(xid=372, flags=[])]
2019-03-19T13:49:00.464574829Z 2019-03-19 13:49:00,464 | WARN | pool-17-thread-1 | DefaultSwitchHandshaker | 163 - org.onosproject.onos-protocols-openflow-api - 1.13.5 | Dropping messages for switch 00:00:00:00:0a:c0:14:ce because channel is not connected: [OFGroupDescStatsRequestVer13(xid=372, flags=[])]